



## Scan hard disk

Turn on power, wait until screen show up Actual Position and then press “▶” and press [EXIT] → Input, “exit system“ use arrow key select “Yes” → Input. They will show up C:\L2000\exe> type: “NDD” → Input → select Diagnose disk → Use spacebar to select all the hard disk C, D and E drive and press Input. Begin test → Input.



Done → Input and Quit disk doctor → Input → C:\L2000\exe. Turn off power.